

NOV 22 2004

5/6




Fig. 5

Typical Response to Operation from
Engine Start Button.